




NOISE MEASUREMENT TEST CHART (STILL VIDEO) 1000:1

TRANSPARENCY



For measuring procedures see ISO 15739 (1000:1)

step	density (ISO)	density chart
1	3.10	
2	2.32	
3	1.84	
4	1.48	
5	1.21	
6	0.98	
7	0.72	
8	0.62	
9	0.47	
10	0.33	
11	0.21	
12	0.10	
13a	1.05	
13b	0.90	
13c	0.77	

Densities based on blank parts of transparency = 100%

Frechen: